


## ZS-LLY Walk-around damage checklist





Comments:

ZS-LLY Right hand side



Comments:

Initial BV Rep:\_\_\_\_\_

Initial Customer:\_\_\_\_\_

Meter	Reading	٨	ITEMS IN AIRCRAFT	Y/N		
Hobbs On:	neuung		Fuel:	1/1		
Hobbs On:			Oil:			
Tacho On:		e ///	Oil Funnel:			
Tacho Off:			Towbar:			
		/    \	Chocks:			
		/    \	Tie Down Rope:			
		/    \	Tie Down Pegs & Hammer:			
		/ \/ \	First Aid Kit:			
		/ / /	Strips:			
		/ • \	Fire Extinguisher:			
			Complete Flight Bag:			
		r = 1	Window Shade:			
11		1 11111				
11						
<u> </u>				)		
		$\nabla$				
		·				
Comments:	Comments:					
Cockpit fittin						
Instrumentat	tion: ADF U/S, DN	/IE U/S, 1" tear in vinyl trim next to	o map pocket, screw cover			
· · /						
missing top LHS instument panel.						

Initial BV	Rep:
------------	------

Initial Customer:\_\_\_\_\_

Comments:		
Buchan Ventures Representative Name:	Signature:	
Customer Name:	Signature:	
Inspection Date:		